




# MXS-21

## PÓŁKA 1D

→ 110 + 50 \ 25



x 13



(a)

x 18



(b)

x 3




(c)

x 21



(d)

x 3 kpl.




(e)

x 2



(f)

x 2




(g)

x 1



(h)



x 4

(3,5x16)



(i)


x 6

(6,2x13)




(j)

x 50



(k)



30 min



1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW

a - OZNACZENIE AKCESORIÓW

1

x 6



(a)

x 6



(b)

x 3



(c)

x 1




(e)

x 2



(j)

(6,2x13)



2

x 2



(a)

x 8



(b)

x 2




(e)

x 4



(j)

(6,2x13)




3

x 2



(f)



4

x 5



(a)

x 4





(b)

x 2




(d)




5

x 10



6

x 9



7

x 2



x 1



x 4  
(3,5x16)



x 50

